

Inspection Photos
Location Name: Simpson FD Pad 15-219HN Facility
Location ID: 440858



Photo #1 Location

Inspection Photos
Location Name: Simpson FD Pad 15-219HN Facility
Location ID: 440858



Photo #2 Separators & Heater Treaters



Photo #3 Tank Battery

Inspection Photos
Location Name: Simpson FD Pad 15-219HN Facility
Location ID: 440858



Photo #4 Production Wells on North Side



Photo #5 Production Wells on South Side

Inspection Photos
Location Name: Simpson FD Pad 15-219HN Facility
Location ID: 440858



Colorado Oil and Gas Conservation Commission
40.48829, -104.87443, 4744.7ft, 87°
01/28/2020 02:45:03 PM

Photo #6 Frac Tanks



Colorado Oil and Gas Conservation Commission
40.48838, -104.87412, 4732.9ft, 222°
01/28/2020 02:54:26 PM

Photo #7 Gas Lift for South Production Wells

Inspection Photos
Location Name: Simpson FD Pad 15-219HN Facility
Location ID: 440858



Photo #8 Gas Lift for North Production Wells



Photo #9 Gas Lift Compressor & Rig Heater

Inspection Photos
Location Name: Simpson FD Pad 15-219HN Facility
Location ID: 440858



Photo #10 “Trash” w/ full trash bin



Photo #11 “Trash” on the west side of trash bin

Inspection Photos
Location Name: Simpson FD Pad 15-219HN Facility
Location ID: 440858



Photo #12 "Trash" around Well

Photo #13 "Trash" around Well

Inspection Photos
Location Name: Simpson FD Pad 15-219HN Facility
Location ID: 440858



Colorado Oil and Gas Conservation Commission
40.48848, -104.87315, 4739.1ft, 191°
01/28/2020 02:56:47 PM



Colorado Oil and Gas Conservation Commission
40.48759, -104.87327, 4758.5ft, 192°
01/28/2020 03:18:34 PM

Photo #14 “Trash” next to Gas Lift compressor north end

Photo #15 “Trash” on East side of sound wall for the VRU’s

Inspection Photos
Location Name: Simpson FD Pad 15-219HN Facility
Location ID: 440858



Colorado Oil and Gas Conservation Commission
40.48739, -104.87455, 4779.7ft, 121°
01/28/2020 03:13:33 PM

Photo #16 “Trash” next to stairs for production tanks



Colorado Oil and Gas Conservation Commission
40.48812, -104.87413, 4744.0ft, 353°
01/28/2020 02:45:45 PM

Photo #17 Unused Equipment next to Frac Tank