

## Inspection Photos

Location Name: LARAMIE ENERGY LLC McDaniel /2-9 Pad

Location ID: 334529



Photo #0482 from entrance to location



Photo #0482 Unused equipment on top of separator.