

Federal RGU 22-6-298
API: 05-103-10603
Inspection: 679707124



Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Federal RGU 22-6-298
API: 05-103-10603
Inspection: 679707124



Photo 2. Separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Federal RGU 22-6-298
API: 05-103-10603
Inspection: 679707124



Photo 3. South side of tank battery.

Federal RGU 22-6-298
API: 05-103-10603
Inspection: 679707124



39.90785, -108.43848, 6461.1ft, 196°
01/27/2020 01:49:32 PM

Photo 4. West water tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Federal RGU 22-6-298
API: 05-103-10603
Inspection: 679707124



Photo 5. Top of west tank.

Federal RGU 22-6-298
API: 05-103-10603
Inspection: 679707124



Photo 6. Side of west tank.

Federal RGU 22-6-298
API: 05-103-10603
Inspection: 679707124



39.90784, -108.43849, 6455.9ft, 261°
01/27/2020 01:50:42 PM

Photo 7. Bottom edge of west tank.