

**Well Name:** Olson Smith GU 2, IGE 127      **API #** 05-067-07911      05-067-09545  
**Inspection Number:** 693901375

**Corrective Action:** Unused risers need lockout/tagout labelling within 24 hours (1/28/2020) and to be removed within 30 days (2/26/2020).  
**Correction Action Due:** 1/28/2020  
**Action Completed:** 1/27/2020  
**Action Taken:** Installed lockout/tagout on risers

