



## Form Information

Form Name: **Compliance Follow Up Form**  
Submitter Name: Cole Nichols (colen@horizonenvservices.com)  
Submission Date: Jan 24, 2020 9:36:27 AM MST  
Server Receive Date: Jan 24, 2020 9:39:00 AM MST  
Reference Number: 20200124-18130729687  
Location: 557 Airpark Dr, Durango, CO 81303, USA  
Jan 24, 2020 9:38:29 AM MST [ [View Map](#) ]

## Information

Name colen@horizonenvservices.com  
Date Jan 23, 2020  
Well Name SIMMONS GAS UNIT A 1  
API Number 50670786100  
Select State Colorado  
Work type COGCC Inspection AR  
Action Complete Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

before removal

Photo of third corrective action completed



Completed work description of corrective action 3  
 Photo of fourth corrective action completed

after removal



Completed work description  
 Completed work description of corrective action 4  
 Additional photos

removal area  
 removed weed debris from reclamation area



Completed work description  
 Summary of all work completed

removed weed debris from reclamation area  
 removed weed debris from reclamation area