



## Form Information

Form Name: **Compliance Follow Up Form**  
Submitter Name: Cole Nichols (colen@horizonenvservices.com)  
Submission Date: Jan 24, 2020 9:56:57 AM MST  
Server Receive Date: Jan 24, 2020 9:59:27 AM MST  
Reference Number: 20200124-18130733226  
Location: 557 Airpark Dr, Durango, CO 81303, USA  
Jan 24, 2020 9:59:07 AM MST [ [View Map](#) ]

## Information

Name colen@horizonenvservices.com  
Date Jan 23, 2020  
Well Name GALLEGOS, BONIFACIO GAS UNIT A 1  
Location Name (Other) Gallegos, Bonifacio Gas Unit A2  
API Number 50670787000  
Location API (Other) 506709059  
Select State Colorado  
Work type COGCC Inspection AR  
Action Complete Clean Up Weed Debris  
Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

Photo of third corrective action completed



location sign

Completed work description of corrective action 3

Photo of fourth corrective action completed



reclamation area

Completed work description

Completed work description of corrective action 4

Additional photos



reclamation area

removed weed debris from reclamation area

Additional photos



Completed work description  
Summary of all work completed

removed weed debris from reclamation area  
initial treatment 4/29/19