



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jan 24, 2020 10:48:47 AM MST
Server Receive Date:	Jan 24, 2020 10:51:16 AM MST
Reference Number:	20200124-18130736613
Location:	557 Airpark Dr, Durango, CO 81303, USA Jan 24, 2020 10:48:43 AM MST [View Map]

Information

Name	colen@horizonenvservices.com
Date	Jan 16, 2020
Well Name	TAYLOR GAS UNIT 21-23 4
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Grading/recontour
Photo of first corrective action completed	



Completed work description Corrective Action 1

construction of a small swale to limit erosion.

Photo of second corrective action completed



Completed work description of corrective action 2

silt bowl with armour outlet.

Completed work description of corrective action 3

na

Completed work description of corrective action 4

na

Completed work description
Summary of all work completed

control runoff into silt trap and outlet
berm, outlet, silt trap.