

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/27/2020

Submitted Date:

01/27/2020

Document Number:

697000478**FIELD INSPECTION FORM**
 Loc ID 304002 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253907	WELL	PR	11/21/1995	GW	125-07785	CURE 22-33	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Pipe fence around unit, wellhead, meter shed, VGS and water tank		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator in metal box		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Type: Pump Jack	# 1	
Comment:	Jensen unit	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		39.668260,-102.187930
Comment:	Fiberglass open top water tank 50% buried				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 253907	Type: WELL	API Number: 125-07785	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing. Casing production			
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Repair erosion leading across location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT