

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2020

Submitted Date:

01/28/2020

Document Number:

689704114

**FIELD INSPECTION FORM**
 Loc ID 335657 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

32 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281383	WELL	PR	11/11/2006	GW	045-11437	N.PARACHUTE EF 15D C28 595	PR
281385	WELL	PR	11/16/2005	GW	045-11438	N.PARACHUTE EF 11D C28 595	PR
281386	WELL	PR	11/22/2006	GW	045-11439	N.PARACHUTE EF03D C28 595	PR
281413	WELL	PR	02/01/2011	GW	045-11455	N.PARACHUTE EF15B C28 595	PR
281414	WELL	PR	11/30/2006	GW	045-11456	N. PARACHUTE EF14D C28 595	PR
281415	WELL	PR	02/01/2011	GW	045-11457	N. PARACHUTE EF11B C28 595	PR
281416	WELL	PR	02/01/2011	GW	045-11458	N.PARACHUTE EF10B C28 595	PR
281417	WELL	PR	11/17/2005	GW	045-11459	N.PARACHUTE EF06D C28 595	PR
282913	WELL	PR	02/13/2007	GW	045-11874	N. PARACHUTE EF03B C28 595	PR
282914	WELL	PR	02/12/2007	GW	045-11873	N. PARACHUTE EF11B- 21C28 595	PR
282915	WELL	PR	02/12/2007	GW	045-11875	N. PARACHUTE EF 10B-21 C28 5	PR
282916	WELL	PR	02/01/2011	GW	045-11872	N.PARACHUTE EF 14B C28 595	PR
282917	WELL	PR	02/13/2007	GW	045-11871	N. PARACHUTE EF 13B C28 595	PR
282918	WELL	PR	07/01/2019	GW	045-11870	N.PARACHUTE EF 12B C28 595	PR

282919	WELL	PR	01/01/2018	GW	045-11869	N. PARACHUTE EF11D21 C28 595	PR
282920	WELL	PR	02/01/2014	GW	045-11868	N. PARACHUTE EF14D21 C28 595	PR
282921	WELL	PR	02/01/2011	GW	045-11867	N. PARACHUTE EF09D C28 595	PR
282922	WELL	PR	02/13/2007	GW	045-11865	N. PARACHUTE EF 13D C28 595	PR
283130	WELL	PR	02/12/2007	GW	045-11896	N. PARACHUTE EF06B C28 595	PR
283131	WELL	PR	02/13/2007	GW	045-11895	N. PARACHUTE EF 12D C28 595	PR
299174	WELL	PR	12/24/2010	GW	045-17588	N. Parachute EF15B-21 C28 59	PR
299178	WELL	PR	12/27/2010	GW	045-17589	N. Parachute EF10D-21 C28 59	PR
299182	WELL	PR	09/30/2010	GW	045-17593	N. Parachute EF15C-28 C28 59	PR
299183	WELL	PR	12/27/2010	GW	045-17594	N. PARACHUTE EF10D-28 C28595	PR
299184	WELL	PR	02/14/2011	GW	045-17595	N. Parachute EF10C-28 C28 59	PR
299187	WELL	PR	01/28/2011	GW	045-17598	N. Parachute EF15A-28 C28 59	PR
299190	WELL	PR	10/03/2010	GW	045-17601	N. Parachute EF10A-21 C28 59	PR
299191	WELL	PR	10/03/2010	GW	045-17602	N. Parachute EF10C-21 C28 59	PR

**General Comment:**

[This is a summary of inspection report.](#)

[On Tuesday 01/28/2020 at approximately 1345 hours, I, Inspector Mike Longworth, conducted a field inspection at CAERUS PICEANCE LLC N.PARACHUTE-65S95W 28NENW C28, at Location # 335657 in Garfield County, Colorado](#)

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	281383	Type:	WELL	API Number:	045-11437	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	281385	Type:	WELL	API Number:	045-11438	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	281386	Type:	WELL	API Number:	045-11439	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	281413	Type:	WELL	API Number:	045-11455	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	281414	Type:	WELL	API Number:	045-11456	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	281415	Type:	WELL	API Number:	045-11457	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	281416	Type:	WELL	API Number:	045-11458	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	281417	Type:	WELL	API Number:	045-11459	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	282913	Type:	WELL	API Number:	045-11874	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282914	Type:	WELL	API Number:	045-11873	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282915	Type:	WELL	API Number:	045-11875	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282916	Type:	WELL	API Number:	045-11872	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282917	Type:	WELL	API Number:	045-11871	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282918	Type:	WELL	API Number:	045-11870	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282919	Type:	WELL	API Number:	045-11869	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282920	Type:	WELL	API Number:	045-11868	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 282921	Type: WELL	API Number: 045-11867	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:		Date:		
Facility ID: 282922	Type: WELL	API Number: 045-11865	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:		Date:		
Facility ID: 283130	Type: WELL	API Number: 045-11896	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:		Date:		
Facility ID: 283131	Type: WELL	API Number: 045-11895	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:		Date:		
Facility ID: 299174	Type: WELL	API Number: 045-17588	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:		Date:		
Facility ID: 299178	Type: WELL	API Number: 045-17589	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:		Date:		
Facility ID: 299182	Type: WELL	API Number: 045-17593	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:		Date:		
Facility ID: 299183	Type: WELL	API Number: 045-17594	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:		Date:		

Facility ID: 299184 Type: WELL API Number: 045-17595 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 299187 Type: WELL API Number: 045-17598 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 299190 Type: WELL API Number: 045-17601 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 299191 Type: WELL API Number: 045-17602 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Compaction	Pass			
Berms	Pass					
				Material Handling And Spill Prevention	Pass	
Check Dams	Pass					

Comment: [Limited BMP inspection due to snow cover.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704115	Inspection 689704114 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051044">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051044</a>