


**Inspection Photos**  
**Location Name: Wild Horse**  
**Location ID: 427410**




**Photo 1 – Tank Battery**



**Photo 2 – Stained Soil at Exhaust**

**Inspection Photos**  
**Location Name: Wild Horse 06-063H**  
**Location ID: 427410**



**Photo 3 – Stained Soil at Engine**



**Photo 4 – Stained Soil at West Counter Weight**

