

Inspection Photos

API: 05-071-09018

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/29/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09018 | Date: 1/29/2020

Inspection Photos



Photo 1. Facing north toward the access road to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09018 | Date: 1/29/2020

Inspection Photos



Photo 2. Facing north along the access road. The side of the road has deeper erosion channel in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09018 | Date: 1/29/2020

Inspection Photos



Photo 3. Facing north along the access road to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09018 | Date: 1/29/2020

Inspection Photos



Photo 4. Facing west at the location. Location has not been recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09018 | Date: 1/29/2020

Inspection Photos



Photo 5. Facing north toward the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09018 | Date: 1/29/2020

Inspection Photos



Photo 6. Facing west at the fill slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09018 | Date: 1/29/2020

Inspection Photos



Photo 7. West side of the location facing northeast toward the cut slope which is approximately 25 ft. vertical cut.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09018 | Date: 1/29/2020