

Inspection Photos

Location ID, Name: 311511 PLATTE 26-2




COGCC Field Inspection
 40.25924, -104.85525, 4701.4ft, 154
 01/29/2020 10:28:3

Photo 1 Battery



COGCC Field Inspection
 40.25918, -104.85496, 4717.8ft, 156
 01/29/2020 10:29:0

Photo 2 Production Equipment



Station #	Ad	Gr	Station Name	Sec	TownShip	Range		
046510	-	-	CLACKY-2A OLSON 2-2	2	4N	20E		
Radio #	Producer Name		Country					
2-20-27121	KPRMC		US					
Transmitter / Module #	Federal #	State #		State				
T110645477				CO				
State / Scan	Up / Down	Diff / Span	Temp / Span	Absolute	API #			
30.0	UP	2-250	2-150	12.2				
Test Date	OP Size	Beta	Sample Date	HrS	Sample Date	HrS	C	Gravity
4-26-12	12.5A	11.0						
8-28-12	12.5A	16.2	8-28-12	5:00				
9-29-12	12.5A	8.2	9-29-12	2:00				
2-12-13	12.5A	12.0	2-12-13	2:00				
3-14-13	12.5A	12.0	3-14-13	2:00				
4-18-13	12.5A	12.0	4-18-13	2:00				
5-20-13	12.5A	12.0	5-20-13	2:00				
7-11-13	12.5A	12.0	7-11-13	2:00				
8-14-13	12.5A	12.0	8-14-13	2:00				
9-27-13	12.5A	12.0	9-27-13	4:00				
10-28-13	12.5A	12.0	10-28-13	4:00				
11-27-13	12.5A	12.0	11-27-13	4:00				
12-16-13	12.5A	12.0	12-16-13	4:00				
1-27-14	12.5A	12.0	1-27-14	4:00				
2-10-14	12.5A	12.0	2-10-14	4:00				

COGCC Field Inspection
 40.25921, -104.85484, 4714.6ft, 294
 01/29/2020 10:31:2

Photo 3 GMR Card Front

