

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> SILVEY 1-27	<b>Facility ID:</b> 114636
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> DAVIS DRILLING INC / 22760	
<b>Updated Operator:</b>	
<b>Form 15 Pit Permit Doc #:</b> 565506	<b>Permit Date:</b> 10/9/1973
<b>Related Facilities:</b> SILVEY (OWP) #1-27 (API 05-009-05311, Facility ID 205562, Loc ID 378946)	

<b>County:</b> BACA			
<b>Township:</b> 31S	<b>Range:</b> 43W	<b>Section:</b> 27	<b>QQ:</b> NWSE
<b>Original Latitude/ Longitude:</b> 37.314851 / -102.247441			
<b>Updated Latitude/ Longitude:</b> /			
<b>Basis for Location Change:</b>			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |   |                  |
|---|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 565506          | Date: 10/9/1973  |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 590563         | Date: 11/10/1994 |
| Doc #: 590559   | Date: 3/24/1995  |
| Doc #: 590553   | Date: 12/13/1996 |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #:              | Date:            |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #:                          | Date:            |
| <input checked="" type="checkbox"/> COGIS Document – Doc #: 590570              | Date: 1/16/1990  |
| <input type="checkbox"/> Pit Inventory – Doc #:                                 | Date:            |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #:                 |                  |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) |                  |
| <input type="checkbox"/> Other:   |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 9/23/1999**

#### Timing of Pit Closure:

Well PA 8/9/1996, passed final inspection 12/13/1996.

#### Pit Status Review Summary:

Based on records review any pits on location were closed prior to 11/10/1994 inspection. Associated well was plugged 8/9/1996 and passed final inspection 12/13/1996. Pit status has been changed to closed.

