

**Inspection Photos**  
**Location Name: Timbro 9-59-8A**  
**Location ID: 456563**




**Photo 1 – Wellheads**



**Photo 2 – Separators**

**Inspection Photos**  
**Location Name: Timbro 9-59-8A**  
**Location ID: 456563**



**Photo 3 – Tank is missing labels – Content, Capacity and NFPA**