

Inspection Photos

1/28/2020

Operator: CHEVRON USA INC # 16700

Location ID: 316636

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



Inspection Photos
Operator Name: CHEVRON USA INC # 16700
Location ID: 316636



Photo 1: Photo taken from the north end of the Location, facing southeast. Photos 1-2 provide an overview of the Location. Photos also show the one active well on Location.



Photo 2: Photo taken from the north end of the Location, facing southwest. See comments under photo 1.

Inspection Photos
Operator Name: CHEVRON USA INC # 16700
Location ID: 316636



Photo 3: Photo shows marker at anchors. All 4 anchors on Location have been marked in accordance with 1003 Rules.



Photo 4: Photo shows cut slope and western areas of the Location. Photo also shows a soil stockpile from the Location. A follow-up inspection will need to be conducted in order to determine compliance with 1003 interim reclamation rules.



Inspection Photos
Operator Name: CHEVRON USA INC # 16700
Location ID: 316636



Photo 5: Photo taken from the south end of the Location, facing north. Photos 5-6 provide an overview of the Location. Photos also show the one active well on Location.



Photo 6: Photo taken from the south end of the Location, facing northeast. Photos 5-6 provide an overview of the Location. Photos also show the one active well on Location.

Inspection Photos
Operator Name: CHEVRON USA INC # 16700
Location ID: 316636



Photo 7: Photo of equipment on the north end of the Location.



Photo 8: Photo of fill slopes and equipment on the north end of the Location.