

**Inspection Photos**  
**Location Name: McWilliams 2-31**  
**Location ID: 312949**



**Photo 1. Photo of access road not maintained for winter access.**

