

Inspection Photos

Location Name: LARAMIE ENERGY LLC Woods Spangler /15-13 Pad

Location ID: 334499



Photo #0487 from entrance to location



Photo #0488 Unused pipe stored on North end of location.