

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2020

Submitted Date:

01/30/2020

Document Number:

689704134

FIELD INSPECTION FORM
 Loc ID 335670 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

26 Number of Comments

1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281864	WELL	SI	09/01/2019	GW	045-11551	N.PARACHUTE EF08B N30 595	SI
281866	WELL	PR	11/02/2006	GW	045-11552	N.PARACHUTE EF02B N30 595	PR
281867	WELL	PR	12/07/2005	GW	045-11553	N.PARACHUTE EF06D N30 595	PR
281868	WELL	PR	11/27/2006	GW	045-11554	N. PARACHUTE EF03B N30 595	PR
281870	WELL	PR	09/25/2006	GW	045-11555	N.PARACHUTE EF02D N30 595	PR
281884	WELL	PR	10/27/2006	GW	045-11556	N.PARACHUTE EF07B N30 595	PR
281887	WELL	PR	12/07/2005	GW	045-11557	N.PARACHUTE EF03D N30 595	PR
281888	WELL	PR	11/27/2006	GW	045-11558	N. PARACHUTE EF06B N30 595	PR
294008	WELL	PR	01/20/2009	GW	045-15200	N. PARACHUTE EF06C-31 N30 59	PR
294009	WELL	PR	08/01/2019	GW	045-15201	N. PARACHUTE EF02A-31 N30 59	PR
294010	WELL	PR	07/06/2008	GW	045-15202	N. PARACHUTE EF02C-31 N30 59	PR
294011	WELL	PR	07/24/2009	GW	045-15203	N.PRACHUTE EF07D-31 N30 59	PR
294012	WELL	PR	08/01/2019	GW	045-15204	N. PARACHUTE EF06A-31 N30 59	PR

294013	WELL	PR	01/12/2009	GW	045-15205	N. PARACHUTE EF03D-31 N30	PR
294014	WELL	PR	01/20/2009	GW	045-15206	N. PARACHUTE EF03A-31 N30 59	PR
294016	WELL	PR	01/07/2009	GW	045-15207	N.PARACHUTE EF08D-31 N30 59	PR
294017	WELL	PR	07/06/2008	GW	045-15208	N.PARACHUTE EF08A-31 N30 59	PR
294018	WELL	PR	07/06/2008	GW	045-15209	N.PARACHUTE EF08C-31 N30 59	PR
294019	WELL	PR	01/06/2009	GW	045-15210	N.PARACHUTE EF07A-31 N30 59	PR
294022	WELL	PR	01/06/2009	GW	045-15211	N. PARACHUTE EF07C-31 N30 59	PR
294023	WELL	PR	01/20/2009	GW	045-15212	N.PARACHUTE EF11A-31 N30 59	PR
294024	WELL	PR	01/20/2009	GW	045-15213	N.PARACHUTE EF11B-31 N30 59	PR
294025	WELL	PR	01/06/2009	GW	045-15214	N.PARCHUTE EF10A-31 N30 59	PR

General Comment:Follow Up Field inspection

On Tuesday 01/28/2020 at approximately 1600 hrs, I, Inspector Mike Longworth, conducted a follow up field inspection at CAERUS PICEANCE LLC N.PARACHUTE-65S95W 30SESW, at Location # 335670 in Garfield County, Colorado
All corrective actions have been addressed from 12/19/2018 Inspection # 689702252.

During this inspection the following possible compliance issues were observed:

Emergency services contact or 911 not posted.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Install sign to comply with Rule 210.b.

C.A. Date 03/01/2020

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign is in clear view.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Emergency services contact or 911 not posted.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	03/01/2020

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 281864	Type: WELL	API Number: 045-11551	Status: SI	Insp. Status: SI
---------------------	------------	-----------------------	------------	------------------

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 281866	Type: WELL	API Number: 045-11552	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action: _____ Date: _____

Facility ID: 281867	Type: WELL	API Number: 045-11553	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action: _____ Date: _____

Facility ID: 281868	Type: WELL	API Number: 045-11554	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action: _____ Date: _____

Facility ID: 281870	Type: WELL	API Number: 045-11555	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action: _____ Date: _____

Facility ID: 281884	Type: WELL	API Number: 045-11556	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action: _____ Date: _____

Facility ID: 281887	Type: WELL	API Number: 045-11557	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action: _____ Date: _____

Facility ID: 281888	Type: WELL	API Number: 045-11558	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	294008	Type:	WELL	API Number: 045-15200 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
Facility ID:	294009	Type:	WELL	API Number: 045-15201 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	294010	Type:	WELL	API Number: 045-15202 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	294011	Type:	WELL	API Number: 045-15203 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	294012	Type:	WELL	API Number: 045-15204 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	294013	Type:	WELL	API Number: 045-15205 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	294014	Type:	WELL	API Number: 045-15206 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	294016	Type:	WELL	API Number: 045-15207 Status: PR Insp. Status: PR

<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 294017 Type: WELL API Number: 045-15208 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 294018 Type: WELL API Number: 045-15209 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 294019 Type: WELL API Number: 045-15210 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 294022 Type: WELL API Number: 045-15211 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 294023 Type: WELL API Number: 045-15212 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 294024 Type: WELL API Number: 045-15213 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 294025 Type: WELL API Number: 045-15214 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				
		Ditches				
Ditches						

Comment: Limited BMP inspection due to snow cover.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	285021	1433412	
	285021	1433412	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704135	Inspection 689704134 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5052588