

Pit Status Evaluation Form

Pit Overview:

Pit Name: STATE OF COLORADO "A-B"	Facility ID: 113694
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: PETROSHARE CORPORATION / 10454	
Updated Operator:	
Form 15 Pit Permit Doc #: 664930	Permit Date: 5/30/1973
Related Facilities: STATE OF COLORADO AB #1 (API 05-001-06455, Facility ID 201052, Loc ID 319709)	

County: ADAMS			
Township: 2S	Range: 66W	Section: 16	QQ: NESE
Original Latitude/ Longitude: 39.87873 / -104.777559			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|--|------------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 664930 | Date: 5/30/1973 |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 664931 | Date: 3/29/1985 |
| | Doc #: 348490 | Date: 6/12/1997 |
| | Doc #: 681700356 | Date: 3/9/2017 |
| <input checked="" type="checkbox"/> | Form 27 Remediation Workplan – Project #: 9695 | Date: 6/17/2016 |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2543035 | Date: 12/27/1995 |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 5/3/2017

Timing of Pit Closure:

Pit closed under remediation project number 9695 - NFA approved 5/3/2017

Pit Status Review Summary:

Records document a 10'x10' production pit on location. Pit closure was performed under remediation project number 9695 (closed 5/3/2017).

