

Inspection Photos  
Location Name: Great Western Pad 8  
Location ID: 333033



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos  
Location Name: Great Western Pad 8  
Location ID: 333033



Photo 3: NFPA placard installed



Photo 4: Trash removed

**Inspection Photos**  
**Location Name: Great Western Pad 8**  
**Location ID: 333033**



**Photo 5: BBLs visible**



**Photo 6: BBLs visible**