

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Photo 1: Tank Battery Signs



Photo 2: Tank Battery



Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Photo 3: NFPA placard installed



Photo 4: Wellhead Sign

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Photo 5: Wellhead



Photo 6: Stained soil removed



Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Photo 7: Wellhead Sign



Photo 8: Wellhead

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026




Photo 9: Stained soil removed