

Inspected FacilitiesFacility ID: 451240 Type: WELL API Number: 123-45035 Status: DG Insp. Status: DG**Well Drilling**Rig: Rig Name: Ensign 147 Pusher/Rig Manager: _____
Permit Posted: _____ Access Sign: _____**Well Control Equipment:**Pipe Ram: YES Blind Ram: YES Hydril Type: _____
Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES**Drill Fluids****Management:**Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
Multi-Well: YES Disposal Location: _____**Comment:** [COGCC Inspection Report Summary](#)
On Thursday 1/30/20 at approximately 1056 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at AD Fed Double Clutch 20W-25-08 of Extraction Oil & Gas, at API # 05-123-45035 in Weld County in Colorado. While there, I observed drilling operations by Ensign 147. Current status was TOO H after performing BOP Test. No violation of COGCC rules were observed at the time of inspection. This is a summary of inspection report. Continuing education inspections

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698700897	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5054128