

Inspection Photos
Location Name: Ewing-Shannon TB
Location ID: 446607



Photo 1 TB sign

Photo 2 TB

Inspection Photos
Location Name: Ewing-Shannon TB
Location ID: 446607



Photo 3 Horizontal Heated Separator

Photo 4 Unused pump removed & Unused flow lines LOTO

Inspection Photos
Location Name: Ewing-Shannon TB
Location ID: 446607



Photo 5 Unused Flow lines LOTO

Photo 6 Unused Flow line LOTO