

Inspection Photos

API: 05-071-08674

Operator: TIMBER CREEK OPERATING

Inspection Date: 1/30/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-08674 | Date: 1/30/2020

Inspection Photos



Photo 1. Well sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08674 | Date: 1/30/2020

Inspection Photos



Photo 2. There is oily waste in the engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08674 | Date: 1/30/2020

Inspection Photos



Photo 3. Facing west at the location. There are some noxious weeds at the location which will need to be controlled next growing season.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08674 | Date: 1/30/2020

Inspection Photos



Photo 4. There is an erosion channel at the northeast side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08674 | Date: 1/30/2020