

# Inspection Photos

API: 05-071-09108

Operator: TIMBER CREEK OPERATING

Inspection Date: 1/30/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09108 | Date: 1/30/2020

## Inspection Photos



**Photo 1.** Facing southwest along the access road. The side of the road has eroded. This area needs to be repaired and BMP's need to be installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09108 | Date: 1/30/2020

## Inspection Photos



**Photo 2.** Well sign is posted at the meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09108 | Date: 1/30/2020

## Inspection Photos



**Photo 3.** There is oil stained soils near the tank and separator. This needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09108 | Date: 1/30/2020

## Inspection Photos



**Photo 4.** There is oily water In the engine skid.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09108 | Date: 1/30/2020

## Inspection Photos



**Photo 5.** Facing south toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09108 | Date: 1/30/2020