

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Hawxhurst Ranch /24-09 Pad

Location ID: 419498



Photo #0511 from entrance to location



Photo #0514 Tank capacity not labeled on methanol tank.

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Hawxhurst Ranch /24-09 Pad

Location ID: 419498



**Photo #0513 Unused chemical tank by wellheads.**

