

Inspection Photos
Location Name: State Antelope J-12 PAD
Location ID: 431415



Photo 1 – Wellheads



Photo 2 – Tank Battery

Inspection Photos
Location Name: State Antelope J-12 PAD
Location ID: 431415



Photo 3 – Separators and Compressors



Photo 4 – Unmarked Risers south of the Tanks