

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/01/2020

Submitted Date:

02/01/2020

Document Number:

696102080

**FIELD INSPECTION FORM**

Loc ID 310259 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291731	WELL	SI	05/01/2017	OW	123-26147	WELLS RANCH USX AA 35-14	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Abandoned. ALL equipment removed.  
Reclamation progressing.  
Abandoned Battery SE corner GPS coordinates: 40.439507, -104.408574

Abandoned Centralized Battery formerly served 3 Location IDs (306643, 310258, 310259).  
(Well(s): 2: Temporarily Abandoned | TA ; 1: Plugged & Abandoned | PA).

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:			Date:
Type: Pump Jack	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead: w/ Master valve.		
Corrective Action:			Date:
Type: Gas Meter Run	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:			Date:
Type: Emission Control Device	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:			Date:

Type: Ancillary equipment	# 0	
Comment: <a href="#">Plugged &amp; Abandoned   PA. Equipment removed.</a>		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment: <a href="#">Plugged &amp; Abandoned   PA. Equipment removed.</a>					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment: <a href="#">Plugged &amp; Abandoned   PA. Equipment removed.</a>					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 291731 Type: WELL API Number: 123-26147 Status: SI Insp. Status: PA

**Workover**

**Comment:** Plugged & Abandoned | PA.  
Well NOT cut / capped.  
Red PTA tag posted.  
Form 42 doc. #402251507 indicates plugging start date: 12/09/2019. Approved.

**Corrective Action:**

**Date:**

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On SAT 02/01/2020 at approximately 09:52 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: WELLS RANCH USX AA-66N63W /35SESW                      Location ID: 310259                      Well Name: Wells Ranch USX AA 35-14                      API: 05-123-26147                      Location County: Weld County, Colorado                      Weather: Partly cloudy.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Battery: Abandoned. ALL equipment has been removed.                      Reclamation progressing.                      Abandoned Battery SE corner GPS coordinates: 40.439507, -104.408574</p> <p>Abandoned Centralized Battery formerly served 3 Location IDs (306643, 310258, 310259).                      (Well(s): 2: Temporarily Abandoned   TA ; 1: Plugged &amp; Abandoned   PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/01/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102081	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055204">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055204</a>