

Inspection Photos

Loc#335551

Operator: Ursa

Inspection Number: 692401847

Inspection Date: 1/24/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to West.

January 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Dever Loc#335551



Photo#2 :
View of weedy Interim Rec area.

January 24, 2020



Photo#3:
View of weedy vegetation on slope area behind equipment.

January 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Dever Loc#335551



Photo#4:
What appeared to be failed repairs of pinholes
observed in battery liner.



Photo#5:
What appeared to be failed repairs of pinholes
observed in battery liner.

January 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Dever Loc#335551