

Inspection Photos

Location Name: LARAMIE ENERGY LLC Gunderson /12-14 Pad

Location ID: 334547



Photo #0521 from entrance to location




Photo #0522 Tank label weathered. Tank capacity is no longer legible.