

Inspection Photos
Location Name: State Antelope D-13 PAD
Location ID: 436098



Photo 1 – Wellheads



Photo 2 – Tank Battery

Inspection Photos
Location Name: State Antelope D-13 PAD
Location ID: 436098




Photo 3 – South Glycol Unit missing Bird Screen



Photo 4 – Unmarked Risers; west of Compressors

Inspection Photos
Location Name: State Antelope D-13 PAD
Location ID: 436098




Photo 5 – Unmarked Risers; East of Compressors




Photo 6 – Stained Soil at West Compressor

Inspection Photos
Location Name: State Antelope D-13 PAD
Location ID: 436098




Photo 5 – Stained Soil at East Compressor