

Inspection Photos
Location Name: Pronghorn P-16 PAD
Location ID: 428090



Photo 1 – Pumping Unit



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Pronghorn P-16 PAD
Location ID: 428090



Photo 3 – South Tank Battery



Photo 4 – North Tank Battery

Inspection Photos
Location Name: Pronghorn P-16 PAD
Location ID: 428090



Colorado Oil and Gas Conservation Commission
40.40778, -104.20714, 4575.4ft, 342°
01/30/2020 13:25:03

Photo 5 – Unused Chemical Tank



Colorado Oil and Gas Conservation Commission
40.407, -104.2073, 4571.2ft, 214°
01/30/2020 13:32:12

Photo 6 – Methanol Storage Tank in SW corner of location