

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/03/2020

Submitted Date:

02/03/2020

Document Number:

696301211

FIELD INSPECTION FORM
 Loc ID 428090 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|-----------------|
| Kraich, Adam | | adam.kraich@state.co.us | |
| , | | EHSRC@bonanzacrk.com | ALL INSPECTIONS |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 428089 | WELL | SI | 11/01/2019 | OW | 123-35220 | State Pronghorn 41-44-16HZ | SI |
| 431200 | WELL | PR | 04/19/2013 | OW | 123-36470 | State Pronghorn 31-34-16HNB | SI |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused Chemical Tank/Pump at 31-34-16HNB Pumping Unit, see photos | | |
| Corrective Action: | Comply with Rule 603.f. | Date: | 03/03/2020 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------|-------|--|
| Type | LOCATION | | |
| Comment: | Barbed Wire | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-------------------------------|-----|-------|-----------------|
| | | | corrective date |
| Type: Gas Meter Run | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|-----------------------------------|-----|-------|
| Type: Horizontal Heated Separator | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bradenhead | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 400 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|-------------|
| | | | | |
| Comment: | Shares berm with the 31-34-16HNB Crude Oil Tanks | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | BV CONCRETE | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 60 BBLS | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|-------------|
| | | | | |
| Comment: | Shares berm with the 31-34-16HNB Crude Oil Tanks | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| METHANOL | 1 | 300 BBLS | STEEL AST | | 40.406870,-104.207380 |
| Comment: | Methanol Storage Tank in SW corner of location. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|-------------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | OTHER | BV CONCRETE | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 60 BBLS | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|---|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | Shares berm with the 41-44-16HZ Crude Oil Tanks | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 200 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|---------------------------------------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | Shares berm with the 41-44-16HZ Tanks | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|-----------|---|----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 3 | 500 BBLS | STEEL AST | | 40.407140,-104.206470 |
| Comment: | | | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|----------------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: 31-34-16HNB Tanks | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|-----------|---------|----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 4 | 400 BBLS | STEEL AST | | 40.408010,104.206560 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|---------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: 41-44-16HZ | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected FacilitiesFacility ID: 428089 Type: WELL API Number: 123-35220 Status: SI Insp. Status: SI**Producing Well**Comment: SI

Corrective Action:

Date:

Facility ID: 431200 Type: WELL API Number: 123-36470 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| Routine Field Inspection. Unused chemical tank/pump at 31-34-16HNB Pumping Unit. | petrie | 02/03/2020 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696301212 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5056166 |