

# Inspection Photos Location Name: Robertson 19-01 #1 API: 05-067-06650



Robertson 19-01 #1 production equipment.



21 bbl. produced water PBV.

**Inspection Photos**  
**Location Name: Robertson 19-01 #1**  
**API: 05-067-06650**



**Linear rod pumps on both well heads.**



**Joint of 6" steel pipe on location. Equipment in background is backfilling excavation for Spill/Release Point ID #470891.**