

Inspection Photos
Location Name: HSR-Guttersen "A" 9-3
Location ID: 329957



Photo #1 Well , Sign & Variance Tag



Photo #2 ECD & No Weeds

Inspection Photos
Location Name: HSR-Guttersen "A" 9-3
Location ID: 329957



Photo #3 Separator, Meter Run & No Weeds



Photo #4 Tank Battery & No Weeds

Inspection Photos
Location Name: HSR-Guttersen "A" 9-3
Location ID: 329957



Photo #5 & No Weeds



Photo #6 & No Weeds