

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402303021

Date Received:

02/04/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10559

Name of Operator: SOUTHLAND ROYALTY COMPANY LLC

Address: 400 WEST 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name Phone

Howe, Mike

Email

MHowe@ctfieldsvcs.com

Hampton, John

JHampton@ctfieldsvcs.com

Blaylock, Connie

CBlaylock@mspartners.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901293

Inspection Date: 12/30/2019

FIR Submit Date: 01/02/2020

FIR Status: _____

Inspected Operator Information:

Company Name: SOUTHLAND ROYALTY COMPANY LLC

Company Number: 10559

Address: 400 WEST 7TH STREET

City: FORT WORTH State: TX Zip: 76102

LOCATION - Location ID: 334050

Location Name: CANDELARIA 32-5-N32N5W Number: 8NENW County: ARCHULETA

Qtrqr: NENW Sec: 8 Twp: 32N Range: 5W Meridian: N

Latitude: 37.037300 Longitude: -107.419200

FACILITY - API Number: 05-007-

-00

Facility ID: 277144

Facility Name: CANDELARIA 32-5 Number: 8-2

Qtrqr: NENW Sec: 8 Twp: 32N Range: 5W Meridian: N

Latitude: 37.037300 Longitude: -107.419200

CORRECTIVE ACTIONS:

1 CA# 135669

Corrective Action: Stormwater erosion needs to be controlled within the project area. Stormwater controls need to be selected, sized, installed, and maintained using good engineering practices such as those described in CDOT manuals for erosion control.

Date: 02/04/2020

Response: CA COMPLETED

Date of Completion: 02/03/2020

Sediment trap re-established; wattles added.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: To control stormwater erosion, the sediment trap was re-established as designed. Wattles were added as erosion barriers.
Photos attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Connie Blaylock

Signed:

Title: Regulatory Analyst

Date: 2/4/2020 1:31:26 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402303045	Corrective Action Photo
-----------	-------------------------

Total Attach: 1 Files