



99999999

WELL SITE INSPECTION FORM

Well Name Stelbar Scott #1 API Number 05 - 081 - 6710
Operator Cockrell Permit # 39-1061
Location SWNE 17-7N-91W County Mottat
Field Craig Inspector BJM
AL/PA/DA Inspection Results: Well Status:
Pass (Y) Fail (N) Date FN FD WO ✓ PR SI

Date of Inspection Before/During Drilling

Surf. Csg. Size Setting Depth Cmt. Vol. WOC time
Consistent with APD casing Program? YES NO Returns
Rig BOP'S Contact

Date of Inspection Before/During/After Completion 8/20/90

Prod. Csg. Set? ✓ Completion Rig/Activity NONE
Drilling Pits: Closed Open ✓ Wellhead Installed: ✓ Sign: Yes ✓ No
Tank ID: Yes No N/A ✓ Skim Tank/Pit: Prod. Tanks: () BBLs
Equipment 320 Pumping Unit w/ Diesel Generator Meter Run: Yes No ✓
Bradenhead Press: Fluid: No Yes ✓ Type H₂O Well Cat. 3c

AL/PA/DA Inspection

Date Plugged: Date Permit Expired:
Hole Plugged: Yes No Pits Backfilled: Yes No
Material Buried: Yes No N/A Site Clean: Yes No
Bond Release OK: Yes No Fed Hole Marker: Yes No

Date of Safety/Status Inspection

Comments: Pumping 500-600 Bbl/Day - Operator plans
on installing a larger pumping unit. Oil leak on
generator - operator will dig a pit + place a
55 gal drum pump.



00221942

Violations: Yes No ✓ Notice Sent: Yes No Date Sent: