



00216736

RECEIVED

FEB 4 1972

COLORADO OIL & GAS COM. COMM.

SAND CONDITIONS"D" SAND

4308-4317 White siltstone

4317-4326 White medium grained, partly clay-filled sandstone, good porosity, no shows.

4326-4342 White fine grained silty and clay-filled sandstone, poor to fair porosity, no shows, occasional shale streaks.

4342-4358 Black silty shale.

"J" SAND

4422-4432 Black silty shale.

4432-4459 White fine to medium grained partly clay-filled sandstone. Good porosity, no shows.

4459-4468 Black shale.

4468-4530 White glassy medium grained, partly clay-filled sandstone with black shale specks, good porosity, no shows.

4530-4547 Same as above with increase in shale.

4547-4553 Black shale.

CONCLUSION

After careful study of the samples and electric logs, this well was plugged and abandoned.

Duane S. Larson
Petroleum Geologist
Certificate #1922 A.I.P.G.
308 C. A. Johnson Building
Denver, Colorado 80202