

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/05/2020

Submitted Date:

02/05/2020

Document Number:

699800526**FIELD INSPECTION FORM**
 Loc ID 450760 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:24 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450749	WELL	PR	07/01/2018		077-10382	Nichols 0994-24-12W	PR
450750	WELL	PR	09/01/2018		077-10383	Nichols Federal 0994-24-20E	PR
450752	WELL	PR	07/01/2018		077-10385	Nichols 0994-24-12E	PR
450753	WELL	PR	08/01/2018		077-10386	Nichols Federal 0994-24-18E	PR
450754	WELL	PR	07/01/2018		077-10387	Nichols 0994-24-11W	PR
450755	WELL	PR	08/01/2018		077-10388	Nichols 0994-24-17W	PR
450756	WELL	PR	09/01/2018		077-10389	Nichols Federal 0994-24-21E	PR
450757	WELL	PR	07/01/2018		077-10390	Nichols 0994-24-10E	PR
450758	WELL	PR	08/01/2018		077-10391	Nichols 0994-24-18W	PR
450759	WELL	PR	08/01/2018		077-10392	Nichols 0994-24-15E	PR
450761	WELL	PR	09/01/2018		077-10393	Nichols Federal 0994-24-19E	PR
450762	WELL	PR	08/01/2018		077-10394	Nichols Federal 0994-24-17E	PR
450763	WELL	PR	07/01/2018		077-10395	Nichols 0994-24-10W	PR
450764	WELL	PR	08/01/2018		077-10396	Nichols 0994-24-13E	PR
450765	WELL	PR	07/01/2018	OW	077-10397	Nichols 0994-24-11E	PR
450766	WELL	PR	09/01/2018		077-10398	Nichols 0994-24-19W	PR
450767	WELL	PR	10/01/2018		077-10399	Nichols 0994-24-21W	PR
450768	WELL	PR	08/01/2018	OW	077-10400	Nichols 0994-24-16E	PR

450769	WELL	PR	09/01/2018		077-10401	Nichols 0994-24-20W	PR
--------	------	----	------------	--	-----------	---------------------	----

General Comment:

COGCC Inspection Report Summary
On Wednesday 2/5/20 at approximately 13:30 hours, I, Inspector Corey De Paolo, conducted an on-site inspection at LARAMIE ENERGY LLC Nichols /24-07, Location #450760 in Mesa County Colorado.
While there, I observed normal production operations.
This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks by wellheads		
Corrective Action:		Date:	
Type: Plunger Lift	# 19		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 19		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	450749	Type:	WELL	API Number:	077-10382	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450750	Type:	WELL	API Number:	077-10383	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450752	Type:	WELL	API Number:	077-10385	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450753	Type:	WELL	API Number:	077-10386	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450754	Type:	WELL	API Number:	077-10387	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450755	Type:	WELL	API Number:	077-10388	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450756	Type:	WELL	API Number:	077-10389	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450757	Type:	WELL	API Number:	077-10390	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	450758	Type:	WELL	API Number:	077-10391	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450759	Type:	WELL	API Number:	077-10392	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450761	Type:	WELL	API Number:	077-10393	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450762	Type:	WELL	API Number:	077-10394	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450763	Type:	WELL	API Number:	077-10395	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450764	Type:	WELL	API Number:	077-10396	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450765	Type:	WELL	API Number:	077-10397	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450766	Type:	WELL	API Number:	077-10398	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	450767	Type:	WELL	API Number:	077-10399	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing](#)

Corrective Action:

Date:

Facility ID:	450768	Type:	WELL	API Number:	077-10400	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing](#)

Corrective Action:

Date:

Facility ID:	450769	Type:	WELL	API Number:	077-10401	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				
		Culverts				
Compaction						
Berms						
Gravel						
Ditches						
		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Tank battery is located on adjacent location Nichols 24-06A location #450791. Refer to document #699800528 inspection conducted on 2/5/20.	depaoloc	02/05/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699800527	Photos for Insp. #699800526	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5058680