


FIRR Photos

Location Name: Babb 15-14

Location ID: 327704



**Photos 1 & 2: View of where debris from former tank battery has been removed**

## FIRR Photos

Location Name: Babb 15-14

Location ID: 327704



**Photos 3: View of leveled ground where production tanks had been set**



**Photos 4: View of area where T-post has been removed**

FIRR Photos

Location Name: Babb 15-14

Location ID: 327704



**Photos 5 & 6: Two views of where contaminated soil on plastic had been and was cleaned up and hauled to disposal**