

## Inspection Photos

Location Name: Anschutz State 5-62-35\_36 NWSW PAD

Location ID: 434251



**Photo 1 – Wellheads**



**Photo 2 – Unused Frac Tank**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Anschutz State 5-62-35\_36 NWSW PAD

Location ID: 434251



**Photo 3 – Unused Rods**



**Photo 4 – Unused Wellhead parts and Pumping Unit**



## Inspection Photos

Location Name: Anschutz State 5-62-35\_36 NWSW PAD

Location ID: 434251



**Photo 5 – Compressor and Separator**



**Photo 6 – Separators**