

Inspection Photos
Location Name: SINJIN E-66N65W /36NESW
Location #: 305188



Photo #1

Sinjin E 36-25 (05-123-22619) Wellsite

Shut-In | SI

Unused Equipment

No LTSI or Decommission TA/SI tags per agreement prior insp.



Photo #2

Sinjin E 36-25 Wellsite

Plugged & Abandoned | PA

~ 25 yds.

Reclamation progressing

Inspection Photos
Location Name: SINJIN E-66N65W /36NESW
Location #: 305188



Photo #3

Sinjin E 36-9, 11, 12, 13, LDS F 1-29 Battery site

Inactive | Shut-down

puddles from rain

prior insp.



Photo #4

Sinjin E 36-9, 11, 12, 13, LDS F 1-29 Battery site

Inactive | Shut-down

Formerly served Sinjin E 36-25

(Plugged & Abandoned | PA)