

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/06/2020

Submitted Date:

02/06/2020

Document Number:

696102144

**FIELD INSPECTION FORM**

Loc ID 305188 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275363	WELL	TA	09/01/2019	GW	123-22619	SINJIN E 36-25	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Inactive | Shut-down.

Centralized Battery serves 5 Location IDs (328688, 302782, 323346, 328685, 328687).  
(Well(s): 5: Temporarily Abandoned | TA).

Centralized Battery formerly served this & 1 other Location IDs (305188, 328686).  
(Well(s): 2: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696100970 and/or Location ID #328688 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696100982 dated 05/31/2019.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Prior insp: SI/TA well per Alternative Mechanical Integrity Assurance Program. Doc #02385001 (NOBLE) . Decommission / LTSI tags for SI/TA status NOT present at wellsite. Install Decommission / LTSI tags for SI/TA status to comply with Doc #02385001. Corrective Action Date: Open  This insp: * Well has been Plugged & Abandoned   PA. ALL signage removed. See photos #1, 2.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Prior insp: Unused equipment (chemical pump & drums) at wellsite. Refer to Rule 603.f. Remove unused equipment (chemical pump & drums) at wellsite. Comply w/ Rule 603.f. Corrective Action Date: 07/03/2019.  This insp: * Unused equipment (chemical pump & drums) at Abandoned Battery site NOW removed. See photos #1, 2.		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:		Date:	

Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 275363 Type: WELL API Number: 123-22619 Status: TA Insp. Status: PA

**Workover**

**Comment:** Plugged & Abandoned | PA.  
Well appears to be cut / capped.  
Form 42 doc. #402199370 indicates plugging start date: 10/07/2019. Approved.  
No record of Form 6S on file as of: 02/06/2020.

**Corrective Action:**  **Date:**

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 02/06/2020 at approximately 11:10 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: SINJIN E-66N65W /36NESW Location ID: 305188 Well Name: Sinjin E 36-25 API: 05-123-22619 Location County: Weld County, Colorado Weather: Mostly cloudy w/ light snow coverage from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged &amp; Abandoned   PA. Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 5 Location IDs (328688, 302782, 323346, 328685, 328687). (Well(s): 5: Temporarily Abandoned   TA).</p> <p>Centralized Battery formerly served this &amp; 1 other Location IDs (305188, 328686). (Well(s): 2: Plugged &amp; Abandoned   PA).</p> <p>Refer to Field Inspection Report doc. #696100970 and/or Location ID #328688 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696100982 dated 05/31/2019. During this inspection, the following prior possible compliance issues appear to be addressed: 1.) SI/TA well per Alternative Mechanical Integrity Assurance Program. Doc #02385001 (NOBLE) . Decommission / LTSI tags for SI/TA status NOT present at wellsite. Install Decommission / LTSI tags for SI/TA status to comply with Doc #02385001. Corrective Action Date: Open * Well has been Plugged &amp; Abandoned   PA. ALL signage removed. See photos #1, 2.</p> <p>2.) Unused equipment (chemical pump &amp; drums) at wellsite. Refer to Rule 603.f. Remove unused equipment (chemical pump &amp; drums) at wellsite. Comply w/ Rule 603.f. Corrective Action Date: 07/03/2019. * Unused equipment (chemical pump &amp; drums) at Abandoned Battery site NOW removed. See photos #1, 2.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/06/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102145	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5059610">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5059610</a>