

## Inspection Photos

Location Name: ROUSE-USX A-66N64W /5NWNW

Location #: 306456



**Photo #1**

**Rouse-USX A 05-19 (05-123-24697) Wellsite**

**Shut-In | SI**

*Invalid Emergency number posted  
prior insp.*



**Photo #2**

**Rouse-USX A 05-19 Wellsite**

**Shut-In | SI**

*Valid Emergency number NOW posted*

## Inspection Photos

Location Name: ROUSE-USX A-66N64W /5NWNW

Location #: 306456



### Photo #3

Rouse USX A 05-03, 04, 05, 06, 19 Battery site

**Inactive | Shut-down**

*prior insp.*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources