

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/06/2020

Submitted Date:

02/06/2020

Document Number:

696102146

FIELD INSPECTION FORM

Loc ID 302562 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@nblenergy.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299538	WELL	SI	09/01/2017	OW	123-29403	ROUSE USX A 05-05	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 5 Location IDs (302563, 302562, 302564, 306456, 414025).
(Well(s): 5: Shut-In | SI).

Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696101668, dated 12/09/2019.

Location			
Lease Road:			
	Type Access		
	comment: Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type WELLHEAD		
	Comment:		
Corrective Action:			Date:
	Type		
	Comment: Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Emergency Contact Number:			
	Comment: Prior insp: Invalid Emergency number posted at wellsite. Refer to Rule 210.b. Post valid Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 01/08/2020. This insp: * Valid Emergency number NOW posted at wellsite. See photos #1, 2.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
	Comment: <input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type		
	Comment: Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment: Iron panel.		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Bradenhead	# 1		
	Comment: Appears plumbed to surface.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.519192,-104.582283
Comment:	Centralized Battery serves 5 Location IDs (302563, 302562, 302564, 306456, 414025). Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 299538 Type: WELL API Number: 123-29403 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
 COGCC records indicate last production: 07/2015.
 SI/TA well per variance Doc #401474555. (NOBLE).
 Yellow LTSI tags for SI/TA status present at wellsite.
 Locked-Out, Tagged Out | LOTO.

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 02/06/2020 at approximately 13:28 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: ROUSE USX A-66N64W /5SWNW Location ID: 302562 Well Name: Rouse USX A 05-05 API: 05-123-29403 Location County: Weld County, Colorado Weather: Mostly cloudy w/ light snow coverage from prior storm.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 5 Location IDs (302563, 302562, 302564, 306456, 414025). (Well(s): 5: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696101668, dated 12/09/2019. During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Invalid Emergency number posted at wellsite. Refer to Rule 210.b. Post valid Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 01/08/2020. * Valid Emergency number NOW posted at wellsite. See photos #1, 2.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/06/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102147	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5060142