

Inspection Photos  
Location Name: William D Lansdown 1  
Location ID: 317613



Photo 1 WH sign



Photo 2 PU/WH

**Inspection Photos**  
**Location Name: William D Lansdown 1**  
**Location ID: 317613**



**Photo 3 unused casing doesn't belong to operator**

**Photo 4 TB sign**

**Inspection Photos**  
**Location Name: William D Lansdown 1**  
**Location ID: 317613**



**Photo 5 TB**



**Photo 6 Produced water**

**Inspection Photos**  
**Location Name: William D Lansdown 1**  
**Location ID: 317613**



**Photo 7 Gas Meter Run**



**Photo 8 Unused flow line tagged out**



**Inspection Photos**  
**Location Name: William D Lansdown 1**  
**Location ID: 317613**



**Photo 9 Horizontal heated separator**



**Photo 10 Vertical separator**

**Inspection Photos**  
**Location Name: William D Lansdown 1**  
**Location ID: 317613**



**Photo 11 Tagged out unused flow lines**



**Photo 12 Weeds have been cut and removed from location**