

Inspection Photos
Location Name: Johnson, Rolland D unit 1
Location ID: 336098



Photo 1 WH sign dead weeds at PU base



Photo 2 PU dead weeds at base

Inspection Photos
Location Name: Johnson, Rolland D unit 1
Location ID: 336098



Photo 3 dead weeds at PU base & WH



Photo4 dead weeds around wellsite ROW