

## Inspection Photos

Location Name: Anschutz State 5-62-26\_25 SWNW PAD

Location ID: 438941



**Photo 1 – Tank Battery**



**Photo 2 – Wellheads**



## Inspection Photos

Location Name: Anschutz State 5-62-26\_25 SWNW PAD

Location ID: 438941



**Photo 3 – Unmarked Risers by Flare**



**Photo 2 – Unmarked Riser by VRT**

