

## Inspection Photos

Location Name: Anschutz State 5-62-27\_34 SESE PAD

Location ID: 421665



**Photo 1 – Pumping Unit, State 5-62-27-0857BH**



**Photo 2 – Pumping Unit, Windmill 4-22H**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Anschutz State 5-62-27\_34 SESE PAD

Location ID: 421665



**Photo 3 – Windmill 4-22H unused wellhead parts**



**Photo 4 – Unused Culverts**