

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Stewart /36-13H (PL36SW)

Location ID: 418660




Photo #0543 from SE corner location



Photo #0544 1000 gallon tank contents and NFPA labels weathered and not legible.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Stewart /36-13H (PL36SW)

Location ID: 418660



**Photo #0545 1000 gallon tank contents and NFPA labels weathered and not legible.**



**Photo #0546 Unused equipment and debris in 1000 gallon tank containment.**